


NUTS

T-GROOVE®



ZINC PLATED

Removable

PART#	SIZE	DRIVE	50	100	1000	BULK
1024.TGN	10-24	#20				
1032.TGN	10-32	#20				
1420.TGN	1/4-20	#20				
518.TGN	5/16-18	#30				
316.TGN	3/8-16	#30				
113.TGN	1/2-13	#40				
511.TGN	5/8-11	#75				
310.TGN	3/4-10	#75				
79.TGN	7/8-9	#100				
18.TGN	1-8	#100				

18.8 STAINLESS STEEL

Removable

PART#	SIZE	DRIVE	50	100	1000	BULK
1024.TGNSS	10-24					
1420.TGNSS	1/4-20					
518.TGNSS	5/16-18					
316.TGNSS	3/8-16					
113.TGNSS	1/2-13					

METRIC

PART#	SIZE	DRIVE	50	100	1000	BULK
M6.10TGN	M6	#20				

Loss Prevention Fasteners & Ultra-Fasteners Inc. ©Copyright 2012. All rights reserved.




**LOSS PREVENTION
FASTENERS™**

P - 1.888.584.6283
F - 1.866.586.7397
E - SALES@LPFAST.COM

NUTS

SLOT-LOK®

HIGH SECURITY




18.8 STAINLESS STEEL

ZINC PLATED

PART#	SIZE	DRIVE	50	100	1000	BULK
440.SLNSS	4-40					
540.SLNSS	5-40					
632.SLNSS	6-32					
832.SLNSS	8-32					
1024.SLNSS	10-24					
1032.SLNSS	10-32					
1420.SLNSS	1/4-20					
1428.SLNSS	1/4-28					
518.SLNSS	5/16-18					
524.SLNSS	5/16-24					
316.SLNSS	3/8-16					
324.SLNSS	3/8-24					
714.SLNSS	7/16-14					
720.SLNSS	7/16-20					
113.SLNSS	1/2-13					
120.SLNSS	1/2-20					
5811.SLNSS	5/8-11					
5818.SLNSS	5/8-18					
3410.SLNSS	3/4-10					
3416.SLNSS	3/4-16					

PART#	SIZE	DRIVE	50	100	1000	BULK
440.SLN	4-40					
540.SLN	5-40					
632.SLN	6-32					
832.SLN	8-32					
1024.SLN	10-24					
1032.SLN	10-32					
1420.SLN	1/4-20					
1428.SLN	1/4-28					
518.SLN	5/16-18					
524.SLN	5/16-24					
316.SLN	3/8-16					
324.SLN	3/8-24					
714.SLN	7/16-14					
720.SLN	7/16-20					
113.SLN	1/2-13					
120.SLN	1/2-20					
5811.SLN	5/8-11					
5818.SLN	5/8-18					
3410.SLN	3/4-10					
3416.SLN	3/4-16					



HEX DRIVE SLOT-LOK® SOCKET
(Call for Socket Sizing)



NUTS

SLOT-LOK®

HIGH SECURITY



18.8 STAINLESS STEEL


Removable

ZINC PLATED

Removable

PART#	SIZE	DRIVE	50	100	1000	BULK
M2.4SLNSS	M2 X .4					
M3.5SLNSS	M3 X .5					
M4.7SLNSS	M4 X .7					
M5.8SLNSS	M5 X .8					
M6.10SLNSS	M6 X 1.0					
M8.125SLNSS	M8 X 1.25					
M8.10SLNSS	M8 X 1.0					
M10.15SLNSS	M10 X 1.5					
M10.125SLNSS	M10 X 1.25					
M10.10SLNSS	M10 X 1.00					
M12.175SLNSS	M12 X 1.75					
M12.15SLNSS	M12 X 1.5					
M12.125SLNSS	M12 X 1.25					
M14.2SLNSS	M14 X 2.0					
M14.15SLNSS	M14 X 1.5					
M16.2SLNSS	M16 X 2.0					
M16.15SLNSS	M16 X 1.5					
M18.25SLNSS	M18 X 2.5					
M18.15SLNSS	M18 X 1.5					
M20.25SLNSS	M20 X 2.5					
M20.20SLNSS	M20 X 2.0					

PART#	SIZE	DRIVE	50	100	1000	BULK
M2.4SLN	M2 X .4					
M3.5SLN	M3 X .5					
M4.7SLN	M4 X .7					
M5.8SLN	M5 X .8					
M6.10SLN	M6 X 1.0					
M8.125SLN	M8 X 1.25					
M8.10SLN	M8 X 1.0					
M10.15SLN	M10 X 1.5					
M10.125SLN	M10 X 1.25					
M10.10SLN	M10 X 1.00					
M12.175SLN	M12 X 1.75					
M12.15SLN	M12 X 1.5					
M12.125SLN	M12 X 1.25					
M14.2SLN	M14 X 2.0					
M14.15SLN	M14 X 1.5					
M16.2SLN	M16 X 2.0					
M16.15SLN	M16 X 1.5					
M18.25SLN	M18 X 2.5					
M18.15SLN	M18 X 1.5					
M20.25SLN	M20 X 2.5					
M20.20SLN	M20 X 2.0					




HEX DRIVE SLOT-LOK® SOCKET
(Call for Socket Sizing)



NUTS

TORK-NUT®



HIGH SECURITY

* NO SPECIAL INSTALLATION TOOLS REQUIRED

ALUMINUM

Non Removable

METRIC

PART#	SIZE	DRIVE	50	100	1000	BULK
1024.TN	10-24					
1420.TN	1/4-20					
518.TN	5/16-18					
316.TN	3/8-16					
113.TN	1/2-13					
511.TN	5/8-11					


PART#	SIZE	DRIVE	50	100	1000	BULK
M6.TN	M6					
M8.TN	M8					
M10.TN	M10					
M12.TN	M12					

Tork-Nuts® are installed with a standard box wrench. Once the hex portion of the nut reaches a specific torque value the hex breaks off leaving you an installed nut with no drive.



NUTS

SNAKE-EYES® / SPANNER®




ZINC DIE-CAST

Removable

METRIC


PART#	SIZE	DRIVE	50	100	1000	BULK
1420.SN	1/4-20	#1				
518.SN	5/16-18	#1				
316.SN	3/8-16	#1				

PART#	SIZE	DRIVE	50	100	1000	BULK
M6.SN	M6	#1				
M8.SN	M8	#1				
M10.SN	M10	#1				



PART#	SIZE	1-9	10 +
1SN.250.3	.250		

.250 SNAKE-EYES® / SPANNER® SOCKET
3 INCH OVERALL LENGTH



PART#	SIZE	1-9	10 +
MSD.250.8	.250		

.250 HEX MAGNETIC SCREWDRIVER
8 INCH OVERALL LENGTH

Loss Prevention Fasteners & Ultra-Fasteners Inc. ©Copyright 2012. All rights reserved.




**LOSS PREVENTION
FASTENERS™**

P - 1.888.584.6283
F - 1.866.586.7397
E - SALES@LPFAST.COM

NUTS

T-SLOPE®

* NO SPECIAL INSTALLATION TOOLS REQUIRED



ZINC PLATED

Removable


METRIC

PART#	SIZE	DRIVE	50	100	1000	BULK
1024.TSN	10-24					
1420.TSN	1/4-20					
518.TSN	5/16-18					
316.TSN	3/8-16					
113.TSN	1/2-13					

PART#	SIZE	DRIVE	50	100	1000	BULK
M5.TSN	M5					
M6.TSN	M6					
M8.TSN	M8					
M10.TSN	M10					
M12.TSN	M12					

INSTRUCTIONS

- #1 - Thread T-Slope® Nut onto bolt hand tight
- #2 - Thread on second T-Slope® Nut upside down
- #3 - Insert Wrench in the middle of both nuts and tighten
- #4 - Once tightened remove the top nut
- #5 - Use the same process to remove nuts



Loss Prevention Fasteners & Ultra-Fasteners Inc. ©Copyright 2012. All rights reserved.



**LOSS PREVENTION
FASTENERS™**

P - 1.888.584.6283
F - 1.866.586.7397
E - SALES@LPFAST.COM